

## REPLACING THE FREE WHEEL ON WHEELS PRIOR TO THE 2013 RANGE

The free wheels M10 M40592 and ED11 M40591 are now replaced by the new free wheels HG11 308 711 01 and ED11 308 713 01.

These new free wheels feature a bearing having an internal diameter of 9 mm, as opposed to 8 mm on previous models.

They are identifiable by their silver-colored bearing protection bearing cap, which was previously black.

A shouldered washer is included in the free wheel kits to ensure the compatibility of these new free wheels with wheels marketed prior to 2013.

It must be used instead of the flat spacer M40066 to install these new free wheels on the old wheels, whose axle (QRM hub) or axle end screw (QRM+ or QRMSL hubs) have a diameter of 8 mm.



The old free wheels M10 M40592 and ED11 M40591, with bearing diameter less than 8 mm and a black bearing protection cap, are not compatible with the new wheels of the 2013 range.